	Туре	L#	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	563	((conveyor with transfer) with (loop or circuit))	USPAT	2003/03/27 10:51
2	BRS	L2	1	1 and (moving near bed)	USPAT	2003/03/27 09:50
3	BRS	L3	15	1 and (transfer near carriage\$1)	USPAT	2003/03/27 09:50
4	BRS	L4	10	("2032934" "2112513" "2218767" "2383736" "2713935" "2905463" "2939450" "3306835" "3384939" "3506755").PN.	USPAT	2003/03/27 10:00
5	BRS	L15	187	1 and (cut\$3)	USPAT	2003/03/27 10:05
6	BRS	L16	1	1 and (cut\$3 with (metal with (piece\$1 or sheet\$1)))	USPAT	2003/03/27 10:03
7	BRS	L17	3	1 and (cut\$3 with (metal))	USPAT	2003/03/27 10:04
8	BRS	L18	184	15 not 16 not 17	USPAT	2003/03/27 10:05
9	BRS	L19	105	1 and (endless with loop)	USPAT	2003/03/27 10:34
10	BRS	L20	35	19 and sheet\$1	USPAT	2003/03/27 10:34
11	BRS	L21	35	1 and (metal with sheet\$3)	USPAT	2003/03/27 10:52
12	BRS	L22	26	21 not 20	USPAT	2003/03/27 10:58
13	BRS	L24	104	23 and (cut\$4 or weld\$3)	USPAT	2003/03/27 11:02
14	BRS	L25	108	(conveyor with transfer with system) and (metal near sheet\$1) and roller\$1	USPAT.	2003/03/27 11:01
15	BRS	L26	73	25 and (cut\$4 or weld\$3)	USPAT	2003/03/27 11:39
16	BRS	L27	5	26 and (close\$3 near loop)	USPAT	2003/03/27 11:44
17	IS&R	L28	19	(83/65).CCLS.	USPAT	2003/03/27 11:44
18	BRS	L23	165	(conveyor with transfer with system) and (metal near sheet\$1)	USPAT	2003/03/27 14:00
19	BRS	L40	59	198/\$.ccls. and ((close\$1 near loop) or (return near loop)) and (metal near sheet\$1)	USPAT	2003/03/27 11:53
20	BRS	L41	22	40 and cut\$4	USPAT	2003/03/27 12:54

	Type	L#	Hits	Search Text	DBs	Time Stamp
21	BRS	L43	1	42 and ((close\$1near loop) or closed-loop)	USPAT	2003/03/27 13:59
22	BRS	L42	31	(method with (cutting with (metal near sheet\$1))) and conveyor	USPAT	2003/03/27 13:39
23	BRS	L44	0	42 and (return\$3 near path)	USPAT	2003/03/27 12:59
24	BRS	L45	13	42 and (return\$3)	USPAT	2003/03/27 13:35
25	IS&R	L46	177	(219/121.39).CCLS.	USPAT	2003/03/27 13:35
26	IS&R	L47	100	(219/121.58).CCLS.	USPAT	2003/03/27 13:35
27	IS&R	L48	139	(219/121.44).CCLS.	USPAT	2003/03/27 13:36
28	IS&R	L49	510	(219/121.48).CCLS.	USPAT	2003/03/27 13:36
29	IS&R	L50	113	(219/121.4).CCLS.	USPAT	2003/03/27 13:36
30	IS&R	L51	62	(219/121.38).CCLS.	USPAT	2003/03/27 13:36
31	IS&R	L52	100	(219/121.41).CCLS.	USPAT	2003/03/27 13:36
32	IS&R	L53	532	(219/121.67).CCLS.	USPAT	2003/03/27 13:36
33	IS&R	L54	355	(219/121.72).CCLS.	USPAT	2003/03/27 13:36
34	IS&R	L55	304	(83/15,16).CCLS.	USPAT	2003/03/27 13:37
35	IS&R	L56	960	(83/170,171).CCLS.	USPAT	2003/03/27 13:37
36	IS&R	L57	178	(83/27).CCLS.	USPAT	2003/03/27 13:37
37	IS&R	L58	1071	(83/155,157).CCLS.	USPAT	2003/03/27 13:38
38	BRS	L59	4010	46 or 47 or 48 or 49 or 50 or 51 or 52 or 53 or 54 or 55 or 56 or 57 or 58	USPAT	2003/03/27 13:38
39	BRS	L60	5	59 and (method with (cutting with (metal near sheet\$1))) and conveyor	USPAT	2003/03/27 13:39
40	BRS	L61	1	60 and ((close\$1 near loop) or closed-loop)	USPAT	2003/03/27 14:00
41	BRS	L62	0	59 and (conveyor with transfer with system) and (metal near sheet\$1)	USPAT	2003/03/27 14:00